

APRIL 2011

DIESEL

EGR Cooler

Connects the Intake Manifold to the Exhaust Manifold to cool exhaust gas before it reaches the EGR Valve



End Caps Upgraded to Stainless Steel for Increased Durability

904-218
Ford 6.0L Diesel
2007-05

FAILURE MODE:

- Extreme temperatures from exhaust gases break down the welded seal on the core inside of the EGR Cooler
- Failure results in a coolant leak inside the exhaust system



Variable Valve Timing Solenoid

Changes CAM timing by controlling oil flow/pressure



917-010
Bravada, Canyon, Colorado, Envoy, Rainier, Trailblazer
2010-02

FAILURE MODE:

- Sludge build up on screens and orifices hinders oil flow resulting in drivability issues
- Electrical failure

Remanufactured Transfer Case Control Modules

Plug & Play for Easy Installation (No Programming Required)



599-104
GM Full Size Trucks (4WD; Push Button Shift(NP8))
2000-98



View Installation Video at DormanProducts.com

Fully Remanufactured & Tested for Quality Assurance

FAILURE MODE:

- Corrosion, components degrade over time
- Will not shift in and out of 4WD

ALSO NEW

599-102
S10, Sonoma (4WD; Push Button Shift(NP8))
2005-99

Upper Shock Mounts

Mounts the Shock Absorber to the frame of the vehicle



924-407
Ford Full Size Trucks, Rear
1997-80

ALSO NEW

924-401
GM Full Size Trucks
2000-88

Vapor Canister Vent Valves



911-650
Baja, Forester, Impreza, Legacy, Outback
2005-98

DIESEL

Fuel Filter Air Bleeders

When Servicing the Fuel Filter, the screw is removed to bleed air from the Fuel System



Contains five Air Bleed Screws

904-112
GM Full Size Trucks
6.6L Diesel
2010-01

FAILURE MODE:

- Stripping of Plastic Threads

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492

APRIL 2011

Seat Heater Switch



901-200
GM Full Size Trucks
2007-03

FAILURE MODE:

- Electrical failure due to corrosion
- Mechanical failure

EGR Tubes



598-201
GM 3.1, 3.4L
1999-96

FAILURE MODE:

- Stress fractures, corrosion and blockage from carbon buildup
- Failure causes poor engine performance, poor fuel economy and can cause the vehicle to fail state emissions tests

Plastic Backed Mirror Glass

Includes backing plate for Snap-In Replacement



14 NEW SKUs!

56114 [L]
56115 [R]
E Series Vans,
Ford Full Size Trucks
2010-00
(Non-Heated)

LINE UPDATES

Wheel Hubs (Flanges)

9 NEW SKUs!



930-466
Accord, CL
1997-90

FAILURE MODE:

- Bearing Race seizes itself to the Hub, Preventing re-use
- Includes axle nut & wheel stud (where applicable)

SubFrame Mount Kits

Rubber Cushion Securing the Subframe to the Chassis



924-011
Sable, Taurus
1995-86

Includes necessary hardware to complete the repair

FAILURE MODE:

- Rubber deteriorates

Intake Manifolds



615-477
Windstar, Lower
2003-99

FAILURE MODE:

- Original units warp from heat, resulting in port leaks

Air (Blend) Door Actuators

7 NEW SKUs!



604-213
Aviator,
Explorer, Ford
Full Size Trucks,
Mountaineer
2009-02

FAILURE MODE:

- Fails due to motor burnout or electrical failure
- Failure causes improper function of the A/C, Heat and/or Defrost

Sockets

Sockets are used with light bulbs and are repaired by cutting the failed plug and connecting the new socket



645-607
Cornering Lamp Socket
Envoy, Grand Prix, Lucerne
Trailblazer 2008-02

FAILURE MODE:

- Melting
- Breaking
- Damage from Impact

Third Brake Lights



923-205
Montana, Silhouette,
Terraza, Trans Sport,
Uplander, Venture
2008-97

FAILURE MODE:

- Corrosion, crash or bulbs burning out

BE THE FIRST TO KNOW!
Sign Up at www.DormanProducts.com/Signup

Customer Service:
1-800-523-2492

APRIL 2011

WINDOW REGULATORS

MOST COMPREHENSIVE PROGRAM IN THE AFTERMARKET

468 Exclusive SKUs

NOW OFFERING
1370
TOTAL SKUs



748-212 [FL]
748-213 [FR]
Ford Full Size Trucks 2003-99
Power Window Regulator w/ Motor



749-186 [FL]
749-187 [FR]
Mustang 2007-05
Power Window Regulator w/o Motor

www.DormanProducts.com/GetMore

BE THE FIRST TO KNOW!

Sign Up at www.DormanProducts.com/Signup

Customer Service:

1-800-523-2492